

Fig. 1

09977622-101501




Fig. 2

09977622-101501




Fig. 3



Fig. 4




Fig. 5




Fig. 6

0997622-10501




Fig. 7

0997622-10501




Fig. 8






Fig. 9




Fig 10

09977622-101501




Fig 11




Fig 12




Fig. 13a




Fig 13b

FIG. 14

Select programming object

Hotel name:

Phone number:

Select programming port

☒ Com1 ☐ Com2  
☐ Com3 ☐ Com4  
☐ Lpt1 ☐ Lpt2  
☐ USB port  
☐ Acctisport

Programming mode

☐ Auto ☒ By hand

Programming fail

☐ Save this message  
☒ Stop auto to hand

Link is fail

Try  times

Help windows

The operation will send the message to the device to be programmed.

Programming status window

PORT ON

Link successful

fig 14

452

HOTEL NAME  
hotel california

Append Delete BackUp Restore

AFGIS 600 FAMILY

☐ 6003S ☐ 6005S ☐ 60010S  
☐ 6001P ☐ 6001S ☐ 6001  
☐ 6001D5 ☐ Other  Add

PHONE NUMBER

Total 7 items 1

11122233344455566677

< < Search > >

Append Save Delete

☒ Question delete ☐ Clear all

Return main screen

456

MEMORY KEY

Message Key 500PP0095

Memory Key 1 03512900

Memory Key 2 120

Memory Key 3 110

Memory Key 4 105

Memory Key 5 205

Memory Key 6

Memory Key 7

Memory Key 8

Memory Key 9

Memory Key 10

Fig 15






Fig. 16




Fig. 17a

